ALUATION PIACE OBTAINED 25X1 TE OF CONTENT. TE OBTAINED DATE PREPARED 2 January 1973 25X FERENCES GES 1 ENCLOSURES (No. & TYPE) MARKS This is UNEVALUATED Information From 10 to 29 November, at the site of the new barracks buildings in Ruedersdorf-Kalkberge (N 53/Z Ol). The skeleton structures were completed except for that of the repair shop. When the sinetailed in the administration building was connected with the various dwellings, the guard house and the repair shop. Work on the heating installation came to a standstill because radiators failed to arrive. This also caused delay in the interior work. The Russian officer who drove sedan frequently appeared at this site to watch the progress of the work.	* * ***********************************		1/26 : CIA-RDP80 TY INFORMATION		001001200	01-9	2
ALUATION PLACE OBTAINED 25X1 TE OF CONTENT. TE OBTAINED DATE PREPARED 2 January 1973 25X FERENCES GES 1 ENCLOSURES (NO. & TYPE) MARKS This is UNEVALUATED Information From 10 to 29 November, 200 laborers were still working at the site of the new barracks buildings in Ruedersdorf-Kalkberge (N 53/Z Ol). The skeleton structures were completed except for that of the repair shop. The glazing work was 75 percent completed. The heating installation which was installed in the administration building was connected with the various dwellings, the guard house and the repair shop. Work on the heating installation came to a standstill because radiators failed to arrive. This also caused delay in the interior work. The Russian officer who drove sedan frequently appeared at this site to watch the progress of the work.					lichawaa		Square on Beauty
THE OF CONTENT. TE OBTAINED DATE PREPARED 2 January 1973 25X FERENCES GES 1 ENCLOSURES (No. & TYPE) MARKS This is UNEVALUATED Information From 10 to 29 November, 200 laborers were still working at the site of the new barracks buildings in Ruedersdorf-Kalkberge (N 53/Z Ol ₄). The skeleton structures were completed except for that of the repair shop. The glazing work was 75 percent completed. The heating installetion which was installed in the administration building was connected with the various dwellings, the guard house and the repair shop. Work on the heating installation came to a standstill because radiators failed to arrive. This also caused delay in the interior work. The Russian officer who drove sedan frequently appeared at this site to watch the progress of the work.	The Committee of the Co	And the second s	and the state of t	CANADA SA MINISTERIO DE SER SA	ALLUGA E. C	reditor (America) province execute and examination en	m in referencement value at all a large 1,00 subjects
THE OBTAINED DATE PREPARED 2 January 1973 25X FERENCES GES 1 ENCLOSURES (No. & TYPE) MARKS This is UNEVALUATED Information From 10 to 29 November, 200 laborers were still working at the site of the new barracks buildings in Ruedersdorf-Kalkberge (N 53/Z Ol). The skeleton structures were completed except for that of the repair shop, The glazing work was 75 percent completed. The heating installation which was installed in the administration building was connected with the various dwellings, the guard house and the repair shop. Work on the heating installation came to a standstill because radiators failed to arrive. This also caused delay in the interior work. The Russian officer who drove sedan frequently appeared at this site to watch the progress of the work.	ALUATION	PIACE OF	BTAINED		Security Supplemental Security	North State and Special States and an	25X1
This is UNEVALUATED Information From 10 to 29 November, at the site of the new barracks buildings in Ruedersdorf-Kelkberge (N 53/Z Oh). The skeleton structures were completed except for that of the repair shop. The glazing work was 75 percent completed except for that of the repair shop. The glazing work was 75 percent completed by the state of the was installed in the administration building was connected with the warious dwellings, the guard house and the repair shop. Work on the heating installation came to a standatill because radiators failed to arrive. This also caused delay in the interior work. The Russian officer who drove sedan frequently appeared at this site to watch the progress of the work.	TE OF CONTENT					TOTAL COMMENTS COMMENTS	25 X 1
From 10 to 29 November, at the site of the new barracks buildings in Ruedersoft-Kalkberge (N 53/Z Oh). The skeleton structures were completed except for that of the repair shop. The glazing work was 75 percent completed. The heating installation which was installed in the administration building was connected with the various dwellings, the guard house and the repair shop. Work on the heating installation came to a standstill because radiators failed to arrive. This also caused delay in the interior work. The Russlan officer who drove sedan frequently appeared at this site to watch the progress of the work.							25X1
This is UNEVALUATED Information This is UNEVALUATED Information This is UNEVALUATED Information 200 laborers were still working at the site of the new barracks buildings in Ruedersdorf-Kalkberge (N 53/Z Ol.). The skeleton structures were completed except for that of the repair shop. The glazing work was 75 percent completed. The heating installation which was installed in the administration building was connected with the various dwellings, the guard house and the repair shop. Work on the heating installation came to a standstill because radiators failed to arrive. This also caused delay in the interior work. The Russian officer who drove sedan frequently appeared at this site to watch the progress of the work.						ina that or suprementation	Michael Control of the Security of Property Control
This is UNEVALUATED Information This is UNEVALUATED Information 200 laborers were still working at the site of the new barracks buildings in Ruedersdorf-Kalkberge (N 53/Z Ol ₄). The skeleton structures were completed except for that of the repair shop. The glazing work was 75 percent completed. The heating installation which was installed in the administration building was connected with the various dwellings, the guard house and the repair shop. Work on the heating installation came to a standstill because radiators failed to arrive. This also caused delay in the interior work. The Russian officer who drove sedan frequently appeared at this site to watch the progress of the work.						and allegate the second of the second	CONTRACTOR OF SECURIOR AND SECURIOR SECURIOR SECURIOR SECURIOR SECURIOR SECURIOR SECURIOR SECURIOR SECURIOR SE
This is UNEVALUATED Information From 10 to 29 November, at the site of the new barracks buildings in Ruedersdorf-Kalkberge (N 53/Z 04). The skeleton structures were completed except for that of the repair shop. The glazing work was 75 percent completed. The heating installation which was installed in the administration building was connected with the various dwellings, the guard house and the repair shop. Work on the heating installation came to a standstill because radiators failed to arrive. This also caused delay in the interior work. The Russian officer who drove sedan frequently appeared at this site to watch the progress of the work.	100				NO THE SECOND PROPERTY OF THE	andre au de antre d'indepopre parente.	Nillion Million had a single a single asset on a single a single asset on a single a single a single a single a
This is UNEVALUATED Information From 10 to 29 November, at the site of the new barracks buildings in Ruedersdorf-Kalkberge (N 53/Z 04). The skeleton structures were completed except for that of the repair shop. The glazing work was 75 percent completed. The heating installation which was installed in the administration building was connected with the various dwellings, the guard house and the repair shop. Work on the heating installation came to a standstill because radiators failed to arrive. This also caused delay in the interior work. The Russian officer who drove sedan frequently appeared at this site to watch the progress of the work.	MARKS	AND THE RESIDENCE AND ADDRESS OF THE PARTY O	Party (National St. Co. Manager St. Co. Co. Co. Co. Co. Co. Co. Co. Co. Co		and the special section of the special section of the special section is	deca secondo de como constituente de constituente de constituente de con	to combine a processor and a responsive to a security (1989 of 1985)
From 10 to 29 November, at the site of the new barracks buildings in Ruedersdorf-Kalkberge (N 53/Z Ol ₁). The skeleton structures were completed except for that of the repair shop. The glazing work was 75 percent completed. The heating installation which was installed in the administration building was connected with the various dwellings, the guard house and the repair shop. Work on the heating installation came to a standstill because radiators failed to arrive. This also caused delay in the interior work. The Russian officer who drove sedan frequently appeared at this site to watch the progress of the work.	THE RESERVE AND THE SECOND PROPERTY AND THE PROPERTY AND	Property of the same and the sa	THE WATER AND THE STATE OF THE		THE REPORT OF THE PERSON NAMED IN COLUMN TO BE ASSESSED.	araya magamata sakarra kada matamatan sakarana	Personal survey of the second
From 10 to 29 November, at the site of the new barracks buildings in Ruedersdorf-Kalkberge (N 53/Z Ol ₁). The skeleton structures were completed except for that of the repair shop. The glazing work was 75 percent completed. The heating installation which was installed in the administration building was connected with the various dwellings, the guard house and the repair shop. Work on the heating installation came to a standstill because radiators failed to arrive. This also caused delay in the interior work. The Russian officer who drove sedan frequently appeared at this site to watch the progress of the work.		. Note to be the property of t	enthalest and higher and glove protein grade and and adding designation that		um ellen å tima sem men em men mel men delege ege	FACE OF CHINESES OF CONTRACT OF THE PASSES	his adiometrality and an appropriate of
at the site of the new barracks buildings in Ruedersdorf-Kalkberge (N 53/Z Ol ₁). The skeleton structures were completed except for that of the repair shop. The glazing work was 75 percent completed. The heating installation which was installed in the administration building was connected with the various dwellings, the guard house and the repair shop. Work on the heating installation came to a standstill because radiators failed to arrive. This also caused delay in the interior work. The Russian officer who drove sedan frequently appeared at this site to watch the progress of the work.		This is UNEVA	LUATED Inform	ation			
at the site of the new barracks buildings in Ruedersdorf-Kalkberge (N 53/Z O4). The skeleton structures were completed except for that of the repair shop. The glazing work was 75 percent completed. The heating installation which was installed in the administration building was connected with the various dwellings, the guard house and the repair shop. Work on the heating installation came to a standstill because radiators failed to arrive. This also caused delay in the interior work. The Russian officer who drove sedan frequently appeared at this site to watch the progress of the work.	K. Arazaran manan 1886-tah manakan menyadan kerapatan dari dan mengan perunakan sebagai dan menan pengan pengan	When the name or much also make and agrantic and agrantic and agrantic and a service a	«Н al (4790-146-) в били невысовника наукулицы экисия	Новетовен и исполни оспозивале.	Sir dhe kanye ing yan Phage (badii ag alii	i fanor - 2002 st.b., dagsags to 2003.0 4464 s electio eg	
at the site of the new barracks buildings in Ruedersdorf-Kalkberge (N 53/Z Ol ₁). The skeleton structures were completed except for that of the repair shop. The glazing work was 75 percent completed. The heating installation which was installed in the administration building was connected with the various dwellings, the guard house and the repair shop. Work on the heating installation came to a standstill because radiators failed to arrive. This also caused delay in the interior work. The Russian officer who drove sedan frequently appeared at this site to watch the progress of the work.			347.3.				2
at the site of the new barracks buildings in Ruedersdorf-Kalkberge (N 53/Z O4). The skeleton structures were completed except for that of the repair shop. The glazing work was 75 percent completed. The heating installation which was installed in the administration building was connected with the various dwellings, the guard house and the repair shop. Work on the heating installation came to a standstill because radiators failed to arrive. This also caused delay in the interior work. The Russian officer who drove sedan frequently appeared at this site to watch the progress of the work.							
	frequently appeared a	it this site to	o watch the pro	gress of	sedan the work	<u> </u>	2
							25
		9					
		,					
				**			
					•		